

Produce the drawing in Autocad, following these steps:

- a. Use the layers as you can see it on the pdf!
- b. Only the model drawing element should be in the model space (lines, hatches, etc.). The annotations, texts, frame, letterhead **NOT!**
- c. Please make the frame, letterhead, annotations, batch numbers only in the layout (in the paper space).
- d. The layout settings: The used printer is "DWG to PDF" virtual printer, the style of the printing is "monochrome". The layout paper size is A3 "ISO A2 (420x594)".
- e. Draw the frame on the layout (550x400), and insert the letterhead.
- f. The scale of the view window is 1:2. (The scale of the **annotation** in the layout is always **1:1!**)
- g. Produce every drawing element (annotation, text etc.).
- h. Print the drawing to PDF, and save it into your working folder.